

## Under Review Notification

**Raised By:** VANESSA MOREL

**Product #:** DART TOOLING AGUSTA

**Date:** 17.11.30

**Product Name:** MULTI-PURPOSE TROLLEY

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	PP Under Review	Product Specifications Under Review ("Bluefiles")		
RBW6005G00131-3G	RBW6005G00131-3G REV 5	Y	Y	N	N	Y			17-763	CAN'T SHIP WITHOUT THE GOOD BOLTS

**Description of Issue:** ASSEMBLY PROBLEM

Item 49 socket cap screws are too short to mount all adapters on top of it.  
 OEM drawing calls up same 49s as Red Barn, but longer screws are shown being used on the accessories that are attached there. Red Barn matches OEM, but OEM is incorrect. Changing item 49 to longer cap screws to allow proper attachment of accessories

RBW6005G00131-3G REV G : ITEM 49 BECOME McM# 91251A628

**Distribution:**

VP Operations Director of Operations Director Quality Assurance Director of Engineering	Chief Engineer Engineering Project Managers Engineering Clerk Customer Support Manager	Production Engineers Production Planners Purchasing Manager Technical Support	Product Manager - Solutions Provider
--	---	--	--------------------------------------